



Test Pieces

Above: Painted Plates

Below: Unpainted Plates

Photo taken on Sept. 16, 2015 -- 2 Years After Subsea Installment of Test Apparatus



Status of Unpainted Test Plates When 12 Months Have Passed After Installment

Left: Test Plate's Side Facing Hirado Strait

Right: Test Plate's Side Facing Breakwater